UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,901,013 B2

DATED

: May 31, 2005

INVENTOR(S) : Jones et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7,

Lines 27 and 31, delete "TO" and insert -- TO --.

Column 8,

Line 30, delete "STOP PD" and insert -- STOP PD --.

Column 16,

Line 43, after "controller" insert -- having a selector --.

Line 43, after "DLL for" insert -- selectively --.

Line 62, delete "clock signal" and insert -- clock signals --.

Column 17,

Lines 5 and 46, after "receiving" insert -- a test --.

Line 60, after "on" insert -- a --.

Column 18,

Line 21, after "receiving" insert -- a test --.

Line 45, after "and the" insert -- test --.

Signed and Sealed this

Third Day of January, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office